



**THE
HONEY
BUCKET
MAN**

P.O. Box 368
Davenport, CA 95017

(831) 335-1393
thehoneybucketman@gmail.com

PAID

INVOICE/JOB WORK ORDER

INSPECTION DATE: 7-27-26
TIME: 9:30
DRIVER: Syone

APN <u>061-023-03</u>	INVOICE # <u>19122</u>	REASON FOR PUMPING: ☐ MAINTENANCE ☒ <u>SALE INSPECTION</u> ☐ HAUL AWAY SYSTEM ☐ OTHER
ORDERED BY <u>Jessica Snyder</u>	WORK PHONE / CELL PHONE	
ADDRESS <u>437 York Ave</u>		
CITY <u>Santa Cruz (Paradise Park)</u>		
OWNERS NAME	PO/WORK ORDER #	
BILL TO (IF DIFFERENT THAN JOB ADDRESS)		

CONDITION OF TANK

SEPTIC ELLS/TEES

TANKTOP/LIDS

SIDES/BOTTOM

BAFFLE

GOOD	FAIR	POOR	REPAIRS RECOMMENDED	REPAIRS COMPLETED
X				
X		XIN	XIN	X 7/29/26
X				
X				

☐ REDWOOD ☒ CONCRETE
☐ PLASTIC ☐ FIBERGLASS

DISTANCE TO TANK: 10'

ELEVATION CHANGE: 0

TANK SIZE: 1500 gal

GALLONS PUMPED: 1500

BOTH SIDES OF TANK PUMPED: ☒ YES ☐ NO

TANK DEPTH: 16" RISERS: Yes DATE LAST PUMPED: 11/1/2020

TANK NOTES/RECOMMENDED REPAIRS: Broken inlet lid. Recommend
new lid. "N" 7-29-26 Install new concrete lid
No further repair required

OPERATION LEVEL:

☐ HIGH
☐ LOW
☒ NORMAL

LEACHING SYSTEM:


PRESENT OR PAST HIGH LEVEL IN TANK? ☐ YES ☒ NO
 LIQUID FLOWBACK WHILE PUMPING? ☐ YES ☒ NO
 SIGNS OF SURFACE EFFLUENT? ☐ YES ☒ NO
 SEPARATE GREY WATER DISCHARGE? ☐ YES ☒ NO

PROPERTY USE:

☐ COMMERCIAL
☒ HOME
☐ OTHER
 OCCUPIED? ☒ YES ☐ NO

LEACHFIELD NOTES/ OTHER SYSTEM COMPONENTS: Passed 250 gal flow test
Within 28 minutes. Flow rate 9 gpm.

DISPOSAL SITE: SCWTP



PUMP COST	<u>725-</u>
LABOR	<u>NC</u>
FUEL CHARGE	<u>25-</u>
LIDS (7/24)	<u>245-</u>
SALE INSP.	<u>200-</u>
CC Processing	<u>\$35.85</u>
TOTAL AMOUNT	<u>\$1230.85</u>



DISCLAIMER: THIS EVALUATION IS BASED ON THE CURRENT CONDITION OF THE SEPTIC SYSTEM AT THE TIME OF SERVICE AND DOES NOT GUARANTEE FUTURE PERFORMANCE. WE WILL NOT BE HELD RESPONSIBLE FOR DAMAGES TO DRIVEWAYS, CONCRETE, AND LANDSCAPING.

CC 7.31.26
Thank You

THE HONEY BUCKET MAN

P.O. Box 368
Davenport, CA 95017
Ph: (831) 335-1393
Fax: (831) 335-1771

Septic System Inspection Report

Ordered By: JESSICA SNYDER

Date: 7-27-26

Property Address: 437 YORK AVE, PARADISE PARK

SANTA CRUZ, CA 95060

APN#: 061-023-03

Depth to Tank: 16"

Risers: ☒ Yes ☐ No **Recommendation:**

Was the tank pumped? ☒ Yes ☐ No

Gallons Pumped: 1,500 GAL

Approximate size of tank: 1,500 GAL

Type of tank: ☐ Redwood ☒ Concrete ☐ Fiberglass **Other:**

Condition of tank and baffles: TANK BAFFLE AND TANK WALLS ARE IN ACCEPTABLE CONDITION

Type and condition of lid: INLET LID IS BROKEN, OUTLET LID IS IN ACCEPTABLE CONDITION

Condition of inlet and outlet T: INLET AND OUTLET T'S ARE IN ACCEPTABLE CONDITION

Required repairs and comments: RECOMMEND REPLACING BROKEN INLET LID

7-29-26 INSTALLED NEW INLET LID—NO FURTHER REPAIRS REQUIRED

Leachfield

Does the level of tank indicate drainfield failure: ☐ Yes ☒ No

Are there wet spots or any other indication of drainfield failure: ☐ Yes ☒ No

Comments: RAN SUCCESSFUL 250 GAL FLOW TEST TO LEACHFIELD (RAN HOSE FOR 28 MINUTES)

Signature: _____

Date: _____

7-27-26

Notice to Buyer: It is not practical to inspect the actual drainfields as they are buried in the ground. The above evaluation only measures the ability of the drainfield to handle the quantity of water / effluent it has been recently processing. It does not insure that it will not fail under a greater load. All drainfields will fail if they receive more water than can be absorbed into the ground immediately surrounding the field.

Septic Tank Pumping Report



County of Santa Cruz
Health Services Agency * Environmental Health

701 Ocean Street, Room 312, Santa Cruz, CA 95060
(831) 454-2022 FAX: (831) 454-3128
TDD/TTY-Call 711 www.scceh.com



**THE
HONEY
BUCKET
MAN**

P.O. Box 368
Davenport, CA 95017
(831) 335-1393
thehoneybucketman@gmail.com

THE HONEY BUCKET MAN

Job Info

Service/Inspection Date: 7/27/2026		APN: 061-023-03
Job Address: 437 YORK AVE, Santa Cruz, CA 95060		
System No: 1	Last Pumped Date: 1/1/2020	Pump Reason/Inspection: Sale Inspection
Requestor Name: Jessica Snyder	Requestor/Owner Email: JessicaSnyder13@ME.com	
Owner Name: Jessica Snyder	Owner Address: 437 YORK AVE, Santa Cruz, CA 95060	
Property Use: Residential	Is Property Occupied: Yes	

Tank Info

Tank Material: Concrete	Tank Size: 1,500	Tank Depth: 16
System Type: Conventional	System Number: 1	Tank Usage: Septic
Gallons Pumped: 1,500	Both Compartments Pumped: Yes	
Condition Septic Ells/Tees: Acceptable	Repair Recommended:	Repair Completed: No
Condition Tank: Acceptable	Repair Recommended:	Repair Completed: No
Condition Tank Top and/or Lids: Unacceptable	Repair Recommended: Broken Inlet Lid. Recommend replacement.	Repair Completed: Yes
Condition Tank Sides/Bottom: Acceptable	Repair Recommended:	Repair Completed: No
Condition Baffles: Acceptable	Repair Recommended:	Repair Completed: No
Operational Level: Normal	Sludge Disposal Location: Santa Cruz Treatment Plant	

Leaching System

Risers Present: No	Risers Water Level:	
Ran Flow Test: Yes	Flow Test Duration: 28	Flow Meter Reading: 250
Liquid Flowback while Pumping: No	Signs of Surfacing Effluent: No	Effluent Location Discharge:
Separate Greywater Discharge: No	Discharge Location:	

Leach System Component Notes: Per Report

Location Information

Tank Location	Water Source Location	Leach Field Begin	Leach Field End
Lat: 0.0000000000000000	Lat: 0.0000000000000000	Lat: 0.0000000000000000	Lat: 0.0000000000000000
Long: 0.0000000000000000	Long: 0.0000000000000000	Long: 0.0000000000000000	Long: 0.0000000000000000

System Location Description: See Drawing

No Second Tank Image :

No Leach Field Image :

No Second Leach Field Image :

Employee Name: Sione Pale

Sione

CUSTOMER COPY

The Honey Bucket Man

6116 Hwy 9

Suite D

Felton, CA 95018

831-335-1393

Terminal: The Honey Bucket Man

Transaction ID: 878986832

Transaction Date: 07/31/2026 05:21 PM (UTC)

Transaction Type: SALE - APPROVED

Card Number: •••• •••• •••• 3052 

AUTH: 07816Z

Invoice: 19122

Order ID: 878986832

Customer ID: Jessica Snyder 437 York Ave, Santa Cruz

Description: POS Septic Inspection

Total: \$1,230.85

Important: Retain this copy for your records